


Add Model to LTspice Symbol

1. Copy Model to C:\Program Files (x86)\LTC\LTspiceIV\lib\sub
2. Open Model to Check .SUBCKT Name
3. Find a Symbol (I.E. opamp1, opamp2) and Place
4. Right Click on Symbol and Set Value Attribute



5. Add a .include Spice Directive to Point at Model File

